# PCS HOT RUNNER MODULE REPAIR

SCAN HERE

FAST, EASY, and ECONOMICAL

- Flat Rate Pricing: $100.00 each (USD) per repair
- Repairable Module Models: VC-M, VC-MP, UATC-20, S20-D3C
- Repair Service Includes: Repair Cleaning and Calibration (no documentation)

INSTRUCTIONS:

Visit https://www.pcs-company.com/pcs-hot-runner-module-repair. Customer to issue P.O. #, and provide Freight Collect # to PCS Company. PCS Company will issue an RGA (Returns Good Authorization) with shipping address. Ship the failed modules to the PCS Company repair center as instructed.

Upon receipt failed modules will be evaluated: If the unit can be repaired, repair will be initiated. If the unit can not be repaired, there will be no repair charge, and the failed unit will be returned freight collect. Repaired units will be invoiced and returned freight collect.