



Turn To The Industry Experts

G-Series Temperature Control Module Repair Service

Fast Easy Economical

All G-Series Modules Repaired All Makes and Models Repaired

Flat Rate Pricing:

\$75.00 ea.	1-10 Modules per repair order	(\$79.00 Canada)
\$65.00 ea.	11+ Modules per repair order	(\$69.00 Canada)

Repair Service Includes:

- Repair
- Cleaning
- Calibration
- Calibration Documentation
- New Packaging

Repair Service Process:

Call PCS Company at 800-521-0546 (ext 1426).

Customer to issue P.O. #, and provide Freight Collect # to PCS Company.

PCS Company will issue an RGA (Returns Good Authorization) with shipping address.

Ship the failed modules to the PCS Company repair center as instructed.

Upon receipt failed modules will be evaluated:

If the unit can be repaired, repair will be initiated.

If the unit can not be repaired, there will be no repair charge, and the failed unit will be returned, freight free.

Repaired units will be invoiced and returned freight collect