





F.I.T.S. Replacement Plates		
Plate	Thickness	Item Number
Support A / Support B, GE Omitted	1.000	2SP-1012-10G
A	1.376	3AT-1012-13
	1.876	3AT-1012-17
	2.376	3AT-1012-23
B	1.376	3BT-1012-13
	1.876	3BT-1012-17
	2.376	3BT-1012-23
Support B, GE Included	1.000	2SP-1012-10
Retainer, GE Included	0.500	2ER-1012-04
Retainer, GE Omitted	0.500	2ER-1012-04G
Ejector, GE Included	0.500	2EP-1012-04
Ejector, GE Omitted	0.500	2EP-1012-04G

www.pcs-company.com