





| F.I.T.S. Replacement Plates          |           |              |
|--------------------------------------|-----------|--------------|
| Plate                                | Thickness | Item Number  |
| Support A /<br>Support B, GE Omitted | 1.000     | 2SP-1014-10G |
| A                                    | 1.376     | 3AT-1014-13  |
|                                      | 1.876     | 3AT-1014-17  |
|                                      | 2.376     | 3AT-1014-23  |
| B                                    | 1.376     | 3BT-1014-13  |
|                                      | 1.876     | 3BT-1014-17  |
|                                      | 2.376     | 3BT-1014-23  |
| Support B, GE Included               | 1.000     | 2SP-1014-10  |
| Retainer, GE Included                | 0.500     | 2ER-1014-04  |
| Retainer, GE Omitted                 | 0.500     | 2ER-1014-04G |
| Ejector, GE Included                 | 0.500     | 2EP-1014-04  |
| Ejector, GE Omitted                  | 0.500     | 2EP-1014-04G |

[www.pcs-company.com](http://www.pcs-company.com)